




GRACE-FO in flight

The twin GRACE-FO satellites will point lasers at each other to track anomalies caused by Earth's gravitational field. <https://dgit.in/Aug18-47-1>



NASA's sun mission

The Parker Solar Probe is a craft with protective shield that is going to "touch" the Sun in a new mission by NASA. <https://dgit.in/Aug18-47-2>



Soldered components

Another shortcoming is soldered components including the processor, RAM and flash memory. All of them have been soldered onto the logic board. Not only does this makes it impractical to repair, but users won't be able to upgrade their MacBook Pros in the future.

MacBook Pro 13 with Touch Bar




Easily-replaceable trackpad

So far, most of the internal design choices of the MacBook has been disappointing. Repairability is terribly poor. However, there's one component that can still be replaced and repaired without breaking your head. The trackpad, just like on the previous model, can be removed just by screws without completely taking the device apart.



Redesigned adapter internals

Compared to the previous power-adapter, the new unit (on the right) has a few design changes on the inside. Additional shielding has been implemented over various components while impact-resistant foam rubber has been added into the empty spaces. The unit should be able to handle drops from a low height.



Images courtesy:

IFIXIT

Website: iFixit.com

Teardown link: <https://dgit.in/McBookPro18>