

Folding glass or plastic?

The truth behind the Samsung Galaxy Z Flip's supposedly physics defying foldable glass.
<https://dgit.in/mar20-31>



Updated Huawei Mate XS

Here's a closer look at the Huawei Mate XS, Huawei's foldable phone offering that folds horizontally. <https://dgit.in/mar20-32>




Hard-to-access flexible display

The flexible, plastic display first needs to be unscrewed from the bottom panel (chin) of the phone. The bendy OLED comes off by removing a few extra screws (from the insides) and extracting it from a metal bracket after using an inordinate amount of tools. iFixit stated that the process was no cakewalk. Even after the OLED display is extracted, the second battery is attached to the display. Replacing either could prove to be a tricky process. The display is likely a Samsung S65Y77CX one, which is one of Samsung's famous touch controllers.



Motorola Razr



Of springs, plates and gears

It's not customary to find mechanical parts inside smartphones, however, with the foldable phone influx we will probably see in 2020, it's about to become commonplace. The new Razr's folding action comprises of parts such as a continuous geared hinge, support plates and a few springs. These units work cohesively to ensure that the fragile OLED display stays protected.

They provide the display support and hold it apart when the phone is open and seamlessly move out of the way to create a large space that prevents the display from creasing too much when closed.



Motherboard and some curious slime

After extracting the first battery behind the rear panel, the motherboard comes into view. However, a regular coin-style vibration motor stands in the way. There's also some strange-looking slime which may be some dielectric grease to add some water resistance to the logic board. The motherboard houses a Qualcomm Snapdragon 710 SoC, Samsung 6GB LPDDR4 RAM and 128GB storage package. It also features two Skyworks modules, one low band and one high band, a radio frequency IC, power management ICs and more.



Website: iFixit.com
 Teardown link: <https://dgit.in/NewMotoRazr>