



Xbox Series X

The availability of a launch title game may have given away the date of the latest Xbox console release. <https://digit.in/aug20-69>



Microsoft Surface Duo

FCC approval means that the launch of Microsoft's dual screen Android phablet may be imminent. <https://digit.in/aug20-70>



Microsoft Surface Pro X




Modular USB ports

Next to the kickstand hinge mechanism and the case buttons lie the modular USB ports and the modular Surface Connect port. This means that they can be replaced easily and independently owing to their modular nature. It is surprising to see so many modular components within one tablet. The glued-down battery is the only weak link when it comes to reparability in the Microsoft Surface Pro X.



The stubborn battery

Sadly, the battery proved to be the most stubborn component in the Surface Pro X since it glued firmly in place, with its connector pinned under the logic board. Removing the battery requires almost complete disassembly. It is a quad-cell, 38.2 Wh battery which is significantly smaller than the Surface Pro 6 (45 Wh), but slightly larger than the 12.9-inch iPad Pro, which features a 36.5 Wh battery.



Examining the silicone

With the heat sink, a few shields, and screws out of the way, the motherboard can be examined. The logic board consists of the following chips – Microsoft SQ1 3.0 GHz ARM processor, Samsung 4 GB LPDDR4X RAM x2, NXP microcontroller, Macronix flash memory, Winbond flash memory, Qualcomm SDR8150 RF transceiver and modem, and Qorvo 78052 14CEM RF Fusion MHB.



Images courtesy:

IFIXIT

Website: iFixit.com

Teardown link:
<https://digit.in/SurfaceProX>