



Accidental reveal

Google accidentally revealed the Pixel Buds A-series TWS in a tweet before taking it down shortly after. <http://digit.in/may21-17>



Dogecoin value surges

Dogecoin surged as much as 50 percent causing the WazirX and Robinhood trading platforms to crash. <http://digit.in/may21-18>

computational power required for validating transactions is reduced drastically. There is no longer any need for miners to buy graphics cards and increase their hash rates. Moreover, anyone who has purchased graphics cards at ridiculously high prices with the intent of turning a profit will have to break even by the end of 2021. After the migration to Proof-of-Stake, there will be no use of their graphics cards. Quite a few miners who've procured their graphics cards at high prices

have started selling their graphics cards to cut their losses. We'll see more of that happening in the coming months. Also, anyone who plans to buy graphics cards now for mining will have to plan out their break-even strategy and focus on a diverse set of coins.

So, you can see how Ethereum will no longer be the driving factor for miners. Bitcoin ceased being lucrative since it requires powerful ASIC Miners to turn a profit. And most of

the other coins aren't worth the effort at the moment. Hopefully, this signals the end of the current crypto-mining craze and the only problems affecting graphics card supplies will be shortage of chips and higher sales.

If not by the end of this year, we should see the prices of graphics cards normalising by early next year. Unless of course, Elon Musk tweets about another cryptocurrency like Dogecoin and sends it skyrocketing to the moon. 

BUYING ADVICE

RYZEN LAPTOP HEATING PROBLEM

Hi Agent001,

I've recently bought an HP Pavilion 15-ec1052AX laptop with the following specs:

- CPU - 3.0 GHz AMD Ryzen 5 4600H
- RAM - 8GB DDR4
- GPU - NVIDIA GeForce GTX 1650 4GB

I've been having some temperature issues whenever I try gaming. I've installed Open Hardware Monitor to log the CPU temp while I'm gaming and it has consistently been around 95-100 °C. Given how the max temp for this AMD processor is 105 °C, I'm really worried that I'll need to manage the temperatures better.

Should I be limiting CPU power usage, or just get a cooling pad? In case it's the latter, please suggest one under ₹2500.

Hope to hear back from you soon.

—Akshit



Hey Akshit,

While it's still within the rated temperature range, 100 °C is quite high. You can take a few steps to reduce temperature including modifying the power plan and getting a cooling pad like you have figured out by yourself. Most OEMs will hide the requisite

power settings and to make it visible, you will have to make a modification to the Windows Registry. To do this, press the shortcut key 'Win+R' to open the Run prompt and type regedit and press the Enter key. This will open the Windows Registry.

Now navigate to HKEY_LOCAL_MACHINE>SYSTEM>CurrentControlSet>Control>Power>Power Settings. The next folder will start with the numbers '5453325' and then within that folder you'll need to find the next folder which will start with the alphanumeric

labelled 'Processor performance boost mode' and change the options for 'on battery' and 'plugged in' to 'Disabled' and click 'Apply'.

By doing so, you have reduced the performance of your processor by a little bit. The processor will now consider its peak level to be a little lower than before and that also means that your process will start to top out earlier. This way it doesn't spend as much time running at the highest possible level and, therefore, will reduce the amount of heat generated. You should check the performance hit in video games. Only stressful tasks like gaming or rendering will be affected by this change. Most of the tasks you perform on a day-to-day basis will remain unaffected.

The other options are to check if you have a BIOS update. Usually, BIOS updates for laptops tend to improve stability and performance a little. Just check the notes of the BIOS update to see if it actually does improve performance. Then you can use the Ryzen Master utility to undervolt the CPU. There are several guides online to do that since it needs a lot more real estate to explain the entire process. The last option is to get a cooling pad. Results vary from laptop-to-laptop and also depend on the ambient temperatures. There are several cooling pads from known brands such as DEEPCOOL available on Amazon. For a gaming laptop, it would be better to get a pad with two fans. Hopefully, these solutions should help. 



HP Pavilion 15-ec1052AX

string 'be337238'. Inside this folder, on the right-hand-side panel you'll see a DWORD entry labelled Attributes. Change the 'Value Data' of this entry from 1 to 2. Once you do this, you will enable additional settings within the Power Plan settings.

Open the Start Menu and type 'Edit Power Plan' and click on the option that shows up. Click on 'Change advanced power settings' to open up the Advanced Settings for the power plan that it selected. Find the option