



### \$3000 bluetooth speaker

Louis Vuitton launches a UFO shaped bluetooth speaker priced at \$2,890. <https://dgit.in/aug21-25>



### Windows Hello bypassed


Hackers trick Windows Hello by hijacking a USB webcam to pass a chosen infrared image. <https://dgit.in/aug21-26>



OnePlus Watch


### The repairability

The OnePlus Watch scored a 5/10 in iFixit's repairability score. While the watch's opening process is pretty straightforward, some things really complicate repairs. The watch has some metal brackets and overlapping cables that can be difficult to work around. The sensor flex is non-removable and attached to the back cover. Additionally, the display is pretty hard to remove and requires heat and special tools.



### Prying off the display

After removing the motherboard and the button liner on the smartwatch, the display can be pried out. It needs some heat to be applied and some careful slicing to be removed though. The 1.39-inch display offers a resolution of 454 x 454 pixels. The display does not come with any digital rotating bezel, as seen on some smartwatches.



### The brains of the device

A few Philips screws hold the motherboard in place and they are pretty easy to remove. The motherboard houses various chips such as the Kingston 4 GB NAND Flash, STMicroelectronics ultra-low-power Arm Cortex-M4 32-bit MCU+FPU, Ambiq Micro Apollo 3 AMA3B microcontroller, Airoha GNSS location processor, Cypress Bluetooth 5.0 SoC, and others.



Images courtesy:

Website: [iFixit.com](https://iFixit.com)

Teardown link: <https://dgit.in/OnePlusWatch>