

EXTERIOR

The finish on early T-34 models was good, but standards dropped as production moved to improvised factories farther east in Russia following the German invasion. The Red Army realized the crude cast marks on the turret made no difference to the tank's fighting ability, so time was not wasted on removing them. The T-34's armor consisted of homogenous rolled and welded nickel steel.

1. Regimental insignia of 4th Guards Tank Corps
 2. Driver's hatch (closed) 3. Co-driver's machine gun
 4. Road wheels 5. Spare track links 6. Axle joint
 7. Fuel cap 8. Commander's (right) and gunner's (left) hatches
 9. Commander's periscope 10. Fuel drum
 11. Exhaust 12. Engine bay

