



INTERIOR

Crew conditions inside the T-34 were very basic but functional. This was due in part to Soviet war philosophy, which saw the tank as a disposable munition, classified along with weapons such as hand grenades or shells. Correspondingly, wartime tanks had an estimated service life of only a few months, and crew comfort was not a priority. However, the T-34/85's expanded turret allowed the crew slightly more room than earlier variants.

13. Looking down into commander's position 14. Spare shells 15. Gunner's periscope 16. Radio 17. Commander's position showing main gun breech 18. Coaxial machine gun 19. Main gun breech (open) 20. Barrel elevation handle 21. Turret traverse handle 22. Fire extinguisher release 23. Driver's position 24. Instrument panel 25. Escape hatch 26. Instrument dials 27. Pressure pump 28. Gearshift