

EXTERIOR

Tanks often feature improvements and additions, and this T-72 from Polish service shows added “gill” armor along the sides. These rubber squares can be angled forward to detonate or disrupt hollow charge rounds before they meet the main body of the tank. The external machine-gun bracket was originally mounted with an anti-aircraft 12.7 mm NSVT, and the turret also housed a 7.62 mm PKT coaxial machine gun.

1. Polish national emblem 2. Station keeping/convoy light 3. Main gunsight
4. Headlight 5. Infrared light 6. Machine-gun bracket 7. Commander's hatch (closed)
8. Gunner's hatch (closed) 9. Deep wading snorkel (stowed) 10. Machine-gun ammunition boxes
11. Engine exhaust 12. Additional “gill” armor 13. Fuel-drum brackets
14. Spare track links on hull 15. Rear reflector

