



INTERIOR

The Centurion differs from World War II tanks in that there is no co-driver—ammunition is stored next to the driver in the place a co-driver would normally have sat. The gunner and commander's gun sights are mechanically linked.

12. Looking down into commander's position
 13. Commander's cupola interior 14. Larkspur radio set 15. Fuses (left) and control box (right) for searchlight
 16. Commander's foot rest 17. Gunner's position 18. Main gun breech 19. Gunner's sight 20. Traverse indicator
 21. Emergency main gun firing panel 22. Elevation handwheel
 23. .50-cal ranging machine gun 24. Driver's compartment
 25. Driver's instrument panel 26. Driver's switchboard