

EXTERIOR

The Mark IV clearly shows the riveted construction of the early tanks—the armor plates were hot-riveted or bolted to a metal framework. The construction meant there were numerous small gaps that allowed bullet “splash” to enter. Crews were issued with masks to protect their faces from hot metal splinters.

1. Tactical number 2. Driver’s vision port (closed)
3. Track tensioner 4. Male sponson with 6-pounder gun
5. Sponson ball machine gun mount (without gun)
6. Location of final drive 7. Track plates 8. Ventilation louvers
9. Rear escape hatch 10. Towing eye

