

EXTERIOR

Because the Light Tank Mark VIB was made before the use of periscopes, the crew had to look directly out of armored vision ports, increasing the risk of injury from bullets or shrapnel. Its external maker's plate has had the manufacturer's details chiseled off the brass—this was to stop a captured tank from revealing the manufacturer's address, which would have been a prime target for a German bomber.

1. Battalion insignia 2. Headlight 3. Spotlight 4. Driver's vision port 5. Fire extinguisher 6. Main machine gun and coaxial machine gun 7. Smoke grenade launcher 8. Commander's vision port 9. Manufacturer's plaque with information removed 10. Exhaust 11. Towing cable 12. Aerial mount 13. Road wheels in paired suspension unit

