



PCB Manufacturers

Please provide a list of PCB manufacturers and PCB assembly services in India.

Kumar Karan Jain
Through email

EFY: You may refer to www.ele2b.com. It is a directory website, where you can get information on electronics vendors including PCB manufacturers and PCB assembly services.

Wireless Communication

This is regarding 'From Sensors to Interfaces-Wireless Communication Has a Lot to Offer' article published in EFY October issue. I am interested in wireless sensors that can replace fibre optical cables used in MRI pulse oximeters. Please help.

H. D. Gandhi
Emco Meditek

EFY: You may contact wireless sensor manufacturers like Texas Instruments, Freescale, Comus, ST Microelectronics and Renesas.

Publish Innovative Projects

I have some innovative projects in working condition and I want to publish them in EFY magazine. Please let me know the format and procedure to submit the same. Will I get any remuneration for the articles?

Asst. Prof. Arjav A. Bavarva
Department of Electronics and
Communications,
School of Engineering,
RK University, Rajkot

EFY: Thank you for your interest in EFY! You may send complete details of the article to editsec@efy.in

The details should include the description of article in .doc format, screenshots/diagrams in .jpg format, source code (if any) in relevant format, and the author's brief detail and contact address in .doc format. Yes, you will get an honorarium for the pub-

'Spot An Error' Award Winners

1. In 'Peripheral Driver with Fixed Regulators 78xx and 79xx DIY' circuit in October issue, on page 96, in the parts list, it should be 7812, 12V regulator instead of 7812, 5V regulator.

2. In 'Weather-Forecast Monitoring System' DIY project in October issue, in Fig. 7, you have not disabled the silkscreen layer before taking output.

Pooja Juyal

□ In '3W USB Stereo Audio Amplifier' DIY circuit in October issue, the footprint of USB-B type in component layout (Fig. 3) is wrong. I have sent the correct orientation of the footprint through e-mail.

Arbab Zafar

□ In '3W USB Stereo Audio Amplifier' circuit in October issue, 3.5mm audio jack pins are interchanged. Pin 1 is for ground, pins 2 and 3 for right and left channels, respectively.

A. Samiuddin

□ In 'Matchbox Capacitor Tester' DIY circuit in October issue, footprints of transistors T1 and T2 in component layout (Fig. 3) are wrong. Transistors T1 (BC558) and T2 (BC548) connections are to be corrected as per the circuit diagram (Fig. 1).

Ramakanta Mohanta

□ In eStyle Buyers' Guide section of October issue, Sky Drive or Google Drive should be read as OneDrive or Google Drive. Microsoft has already changed its cloud service name to OneDrive from SkyDrive.

Nirakar Mahanta

From Facebook: EFY's Electronics Design Community

Can you share some sensitive clap-switch circuits? I had made one that uses BC547 and IC 555, along with a condenser MIC, but it is not working.

Vivek Ghosh

EFY: You can get related circuits from here: http://electronicsforu.com/new-electronics/lab/search_lab.asp?words=clap

□ I have done projects from EFY like LED Emergency Light, Magic Eye and Seven-Colour LED Lighting Using RGB LED. Big thanks to EFY for publishing such wonderful circuits!

Tanmay Dasgupta

lished articles. For details on editorial guidelines, you may refer to http://efymag.com/Guidelines_for_EFY_authors.doc

Emergency Light

In Desktop LED Emergency Light DIY circuit published in September issue, in the sentence 'Resistor R4 limits the base current of transistor T2 and capacitor C3 improves the circuit efficacy,' the word 'efficacy' should be 'efficiency.'

Praveen. S.

Through email

EFY: Thank you for your interest in

our DIY Circuits section. In this circuit, capacitor C3 improves the efficacy and not the efficiency of the circuit.

Access Control

In 'RFID Based Access Control Using Arduino DIY' project published in October issue, CON2 is mentioned in parts list but not in the circuit diagram.

Loveleen kumar

Through email

EFY: All connectors (CON1, CON2, CON3, ..., etc) are either shown in the circuit diagram or PCB layout, or both. In this project, CON2 is used in the PCB and so it is not a factual error.