




Fig. 5: Sprint-Layout components library



Fig. 6: Sprint-Layout-Reticule with automatic-capture mode

produce professional-quality boards. With your own CNC milling machine, Sprint-Layout is also able to create HPGL files for isolation milling.

Sprint-Layout is equipped with tools to draw pads, tracks, copper areas, labels and so on. Just select the corresponding mode and place your elements. All parameters like track width and pad size are visible at a glance, and can be edited every time. The active grid-capture lets you easily

place your elements precisely.

The new version, 6.0, is quite comfortable to use. It offers a user-friendly operation by including many new features and improvements. It is also fully compatible with all the previous versions of Sprint-Layout. This means that you can load all the older layout files and edit them with the new version.

Free viewer option allows everybody to view or print your layouts.

Editing the existing layout elements is very easy and the results are immediately shown after editing. For example, if you adjust the width of a track, you will see the result immediately on your layout. Additional functions like copy, move, rotate and mirror are self-evident.

The tool includes the following important features:

**Component-library.** Many commonly used components are available in

component-library. They can either be SMD or conventional through-hole type. The time spent in searching a component is reduced as the library is displayed in a well-sorted tree view.

**Anti-aliasing.** Anti-aliasing technology improves the screen quality by smoothing the edges.

**Autorouter.** A simple point-to-point autorouter integrated in Sprint-Layout can connect two points of your layout.

**Reticule with automatic-capture mode.** Automatic-capture mode makes it easy to place pads or tracks. The reticule also has a numeric display of the current coordinates.

**Photoview.** This feature helps you find typical mistakes like wrong mirrored components or text. With this, you can take a look at your board as if it was already manufactured with drills, silk screen, etc. X-ray feature can make the board transparent to view the other board-side shine through.

**Free rotation.** You can rotate all the components or elements in any angle. This makes it possible to place your components in the best possible manner.

**Automatic ground-plane.** This feature fills unused areas of a layout with copper automatically. This accelerates the corroding process while saving corroding material. You can also use this function to create a screen for HF boards. You can also define thermal-pads on the automatic ground-plane.

**Test-function.** This function is very helpful to check your layout. Clicking any position of the layout allows you to find and highlight all the connected layout elements. This makes it very easy to check signal flow of the layout.

**Several boards.** A Sprint-Layout file can contain several boards. This allows you to add all the boards of a project to one file. With a single click you get access to any board of your project.

**Footprint wizard.** Footprint wizard helps you create special footprints for components. On specifying the footprint type and parameters, the wizard creates your footprint automatically, which you can place on your layout.

**Design rule check (DRC).** Sprint-Layout is able to check some important design rules, e.g., the minimum clearance distance between two copper tracks. DRC lists all the problems detected in the PCB in clear text, marking all the problem areas. This allows