



FEEDBACK

YOUR SUGGESTIONS

EFY NEW LAYOUT DESIGN

The new layout of EFY January issue is amazing. It is very attractive. EFY covers the latest technology and new products. I love DIY section and open source materials in every issue. I am very thankful to EFY!

Samiuddhin

Through email

EFY. Thanks for the feedback! Your feedback is important to us for improvement and to make a difference in a better way. We highly appreciate your support for the benefit of our readers and look forward to hearing from you in the future, too.

THANKS!

I thank EFY circulation team for their swift action and support. I made a complaint regarding non-receipt of December issue. I received the issue within three days!

V. Nagaraj

Through email

EFY. Thanks for the feedback!

FIRST LOOK

In eStyle First Look section in December 2015 issue, specification for OnePlus X by OnePlus is wrongly mentioned. It should be 2.3 quad-core system on chip, instead of 2.3 quad-core CPUs.

Ravichandra Metri

Through email

EFY. We normally get all data from the original manufacturer's website. Specifications printed in the article are clearly mentioned on OnePlus website.

QUIZ SECTION

I am a subscriber to EFY and it is very

helpful. It is great that I could work on a number of projects based on DIY section. I request you to increase the number of articles that include details on the working of sensors.

I also request you to include a quiz section based on the articles and interviews in the current volume.

Mohammed Shan H.

Through email

EFY. Thanks for the feedbacks and suggestions!

FREQUENCY SHIFT KEYING

In 'Frequency Shift Keying Communication Simulator' article published in

'Spot An Error' AWARD Winners

In 'Things You Wanted to Know' Q&A section of December 2015 issue, under Q2, details related to the Bluetooth module and Bluetooth dongle including Figs 1 and 2 are wrong. Fig. 1 should be HC-05 module. Fig. 2 should be Bluetooth dongle and not as mentioned in the third paragraph. Also, there is no figure of BT 24 module as explained in the second paragraph.

Darshan Shah

In 'Joystick Based Stepper Motor Angle Controller using AVR MCU' article published in December 2015 issue, there is mismatch between Figs 1 and 4. In Fig. 4, pins 5 and 6 of LCD should be connected to ground and PC1 of MCU, respectively. In Fig. 1, VR1 should be connected to 5V and pin 15 of LCD should be connected to 5V through resistor R2.

Ramakanta Mohanta

In the PCB layout of 'Sensing Peripheral Devices with MC1489A Receiver' circuit published in December 2015 issue, Jumper J2 shorting the tracks of RC1 and RC2 is wrong.

Samiuddhin

From electronicsforu.com

Circuits and Microcontrollers

I will try making 'Ultrasonic Radar Model Using Microcontroller ATmega128' circuit published in February 2015 issue. Thank you for sharing the information!

Brij

EFY. Thanks for the feedback!

In 'Motion Detector Using NE555 Timer' article published in August 2015 issue, what is TP0 to TP2. Where can I get the PIR module?

Rakesh Kumar

EFY. TP0 through TP2 are test points. Voltages given in Test Points table may be helpful for beginners during troubleshooting. PIR modules are easily available in electronic component shops. In New Delhi, you can get these from Lajpat Rai Market. PIRs like HC-SR501 modules are easily available online on websites such as www.ebay.in

I liked '12V Battery Absorb and Float Charger' circuit published in September 2015 issue. Which tool is used for designing the PCB? Can you send the complete kit of this project?

Praveen

EFY. We used eEDA software for designing the circuit and PCB layout. The complete kit of this project is not available with us right now. However, you may check www.kitsnspares.com for similar projects.

December 2015 issue, the simulator code is not given.

Rakesh

Through email

EFY. There is no source code used in this article. However, Multisim simulation file is used that is already included in the DVD accompanying the relevant *EFY Plus*.