

Battery

Installation

Tips

To obtain peak performance, batteries connected in a string must be of the same type, make, capacity and age.

The interconnecting cables should also be of appropriate length and cross section.

www.relicellbattery.com



VRLA and Tubular batteries

VRLA Batteries - 12V 7AH to 250 AH
Tubular Batteries - 12V 40AH to 210 AH

Part of a Rs.1000 crore IT industry group
Tested and certified by Central Power
Research Institute, Bangalore (CPRI) and
Electronic Test and Development Centre
(ISTQC Directorate, Ministry of Information
Technology, Govt. of India). **Download Test
Certificates at www.relicellbattery.com**
UL Certified

VRLA Batteries approved and registered in
DGS&D for government purchases
47 Service Centres across India

RELICELL

Greenvision Technologies Pvt.Ltd

45/1, 4th Cross, Mallaswaram, Bangalore - 560 003.
Tel: +91 080 4245 9459, Fax: +91 080 4245 9460.
Email: info@relicellbattery.com

3-D TV in India

In April issue of EFY, there was a news item titled 'India not ready for 3-D yet.'

You may be aware that recently IPL cricket matches were also shot in full 3-D and transmitted on experimental basis. Those who have seen (as published in local newspapers) were left speechless with live transmission in full 3-D. Small countries like Japan, Taiwan and Korea cannot undermine our country's capabilities and potential. Many Bollywood film makers are planning to make movies in 3-D.

Through your powerful magazine, we want to convey the message "Yes, India is ready for 3-D TV."

Suresh Kumar Garg
Dispro Visual Technologies

EFY Projects

Many of the circuits published in EFY are now available on various websites without the name of the magazine or the author. They simply scan the circuit diagram and publish the same as their own circuits. EFY watermarking in all the circuits may prevent violation of copyrights.

D. Mohan Kumar
Through e-mail

☐ Kindly suggest me some good books to help me assemble my own circuits.

Vipin Tiwari
Through e-mail

☐ I am a teacher and interested in electronic projects for middle-school students. Please tell me where can I get the list of available projects and the cost of each project.

Anil Kumar
Mussoorie

EFY: You may refer to *Chip-Talk* book published by EFY. It is meant for hobbyists and beginners and available along with PCBs and components of 40 tested projects. You may also visit www.kitsnspares.com for more projects.

Electric Bike

Please tell me where can I get the circuit for an electric bike (e-bike).

Vijay S. Powar
Thane

☐ I have bought a battery-operated e-bike and request you to publish the circuit of e-bike drive motor mechanism and controller.

A. Veelu
Salem

EFY: We will try to publish the same as soon as we receive a suitable article on the subject.

Voltage Stabiliser

I want to congratulate Adeeb Raza, the author, and EFY for the 'Solidstate Voltage Stabiliser' construction project published in January issue. It was quite practical and informative. I also want to know more about design of the auto-transformer used for 1kVA load.

Sanal Kumar
Bengaluru

RPM Counter

I am facing problem in implementation of the 'RPM Counter Using AT89C4051 Microcontroller' project published in Oct. 2009 issue of EFY and have following queries:

1. In the 'C' language program, the input ports of the MCU (P3.3 and P3.4) are not specified. Also, the writemcd function is never called.

2. I am using AT89C2051 instead of AT89C4051. Will this require change in the program code?

3. After hardware implementation and compilation with Kiel μ Vision 3 compiler, the 16x2 LCD displays only 'RPM Counter.'

Please help.

Unmesh Khatri
Nagpur

The author A.M. Bhatt replies:

1. I don't understand your query on ports, so kindly elaborate. The writemcd function is used to send commands to the LCD. It is called in the main function to initialise the LCD.

2. You can't use AT89C2051 in place of AT89C4051, as it has an EEPROM of 2 kB. The hex file generated by Keil exceeds the 2kB limit, so you have to use AT89C4051.

3. Your hardware will work when an interrupt is generated. So check whether the 555 timer circuit generates the interrupt.