

FEEDBACK

YOUR SUGGESTIONS

PROJECT REPORT

I have been a regular reader of EFY since childhood, and now I am an electronics professional. Project Report is extremely helpful for entrepreneurs like me. I request you to publish a report on PCB fabrication plant for single and double-sided PCBs.

Jaywardhan Pandit

Through email

EFY. Thanks for the feedback! We are glad to know that Project Report is helpful to you. We will try to cover a report on PCB fabrication plant in one of our forthcoming issues.

HEALTH CARE

The 'How Accurate Are Non-Invasive Blood Glucose Meters' article published in October issue is useful to diabetic patients. The article is quite interesting!

O. Subrahmanyam

Through email

EFY. Thanks for the feedback!

FACE DETECTION

This is regarding 'Real-Time Face Recognition Using Python-openCV' DIY article published in April 2017 issue. I recently downloaded the source code for this project. When I run the code, I get some indentation errors. I am new to Python. Error messages are related to the code given below.

```
if faces:
    face_i = faces[0]
    (x, y, w, h) = [v * size for v in face_i]
    face = gray[y:y + h, x:x + w]
    face_resize = cv2.resize(face, (im_
width, im_height))
    pin = sorted([int(n.find('.')) for n
in os.listdir(path)
    if n[0] != '.' ] + [0])[-1] + 1
    cv2.imwrite('%s/%s.png' % (path,
pin), face_resize)
    cv2.rectangle(im, (x, y), (x + w, y +
h), (0, 255, 0), 3)
    cv2.putText(im, fn_name, (x - 10,
y - 10), cv2.FONT_HERSHEY_PLAIN, 1,
```

The 'LED Scrolling Display' article available on <https://electronicsforu.com> is interesting and nicely explained!

Nautec

Kindly send me the code in C for 'LED Scrolling Display' project.

Mutema

EFY. Thanks for the feedback! The program is written in Assembly language. So we do not have C program for this project.

In 'Lossless Image Compression Using MATLAB' DIY article available on <https://electronicsforu.com>, how can I decompress it?

Pankaj

The author Lalit Patil replies:

Once it is compressed, you cannot decompress it with this program. This is because you have modified pixels in mathematical form. Compress and decompress is only reduction in size of the image without reducing quality. So you do not need to decompress again.

In 'Motion Detector Using NE555 Timer' DIY article available on <https://electronicsforu.com>, when I power it on, the relay gets activated. When I remove the sensor, the relay does not get de-energised. The circuit does not reset.

Sooraj

```
(0, 255, 0))
time.sleep(0.38)
count += 1
```

Varun

Through email

EFY. Python code blocks are defined by their indentation. That is, these get structured through indentation. If a block has more deeply-nested code, it is simply indented further to the right. You may use a free text editor such as Gedit and Notepad++ to get proper code indentation. Get more details on

From electronicsforu.com

Electronics Projects

EFY. When power is switched on, the relay energises for around 10 minutes. If relay is not de-energise even after 10 minutes, check whether transistor BC547 is faulty or connected in a wrong position. If it is OK, check IC2.

The 'IoT Home with Hindi Voice Commands using Google Assistant and ESP32' DIY article available on <https://electronicsforu.com> has interesting information on vehicle safety. Thanks a lot for sharing the project!

Imran

I have a couple of queries regarding 'IoT Home with Hindi Voice Commands using Google Assistant and ESP32' project. What is the cost of this project? Assuming the software suggested is open source, please share the approximate cost of the components listed there?

Joan

In 'IoT Home with Hindi Voice Commands using Google Assistant and ESP32' project, how do I add more devices to it?

Arnav Dayal

EFY. Thanks for the feedback! This project costs around US\$ 20.

To add more devices, add more switches to the dashboard on Adafruit website, <https://io.adafruit.com>

Python programming from the following website:

www.tutorialspoint.com/python/python_basic_syntax.htm and www.python.org/about/gettingstarted/

Errata

In 'Washbasin Mirror Light Controller' article published in October issue, please read the rating of the relay (RL1) as 5V single-changeover instead of 12V as mentioned in the article.

Riju Thazhathu Veetil
The author