



External power supply

Optional, if no other power supply available

MCU (SI01)

3V3 Volt required either via: + external power supply (3V3) + energize MCU with 60VDC + energize MCU with3V3 from J-Link (if capable)

2x10pin female header

SEGGER J-LINK (JTAG / SWD)

> TITLE: JLink MCU flash cable **Document Number:** REV: Date: 09.04.21 10:54 Sheet: 1/1