

Captains-Report B737-B767



To: B737-B767 Chief Pilot / Director Flying Operations

FROM CAPTAIN:	F/O	OTHER
Joe Rizzi	Meareg	Abdu, Dagmawit
Departure	Arrival	
OMSJ	VABB	

THE FOLLOWING ARE COMMENTS OR DISCREPANCIES CONCERNING:

FLIGHT NUMBER:	Aircraft Reg	Fleet Type	DATE:
3610	ET-BBF	B767	2025-10-03
☐ FLIGHT CONTROL AND BRIEFING		☐ STATION AND PAX HANDLING	
☒ AIRPORT AND GROUND EQUIPMENT		☐ TRAFFIC AND COMMUNICATIONS	
☐ SAFETY INFORMATION		☐ CREW PERFORMANCE AND IN-FLIGHT SERVICES	
☐ MAINTAINANCE(OTHER THAN FORM 1 ITEM)		☐ SCHEDULE AND DEVIATION	
☐ GENERAL INFORMATION AND SUGGETIONS		☐ HAZARD REPORT	

Please Advise if you Record the Same Report on Maintenance Logbook

Recorded to Logbook?	Logbook No.
YesNo	

COMMENTS

After landing in BOM a cargo stand was provided to us. The stand was G3. Upon arrival to the stand there was no marshaller and no visual docking guidance system. I decided to turn into the stand a little bit and wait for the marshaller to arrive. An engine was shut down as well. The aircraft pointed in towards the stand. Then, the ground controller changed the parking stand to S3 (behind us). It was at this point that we decided that it wasn't possible anymore to maneuver the aircraft. Basically we became stuck at our position. A towbar and pushback truck was required. As a result it turned into a 30 minute delay. A lesson was learned and in the future I will never turn into a stand unless we are confident that we can complete the parking.

