




ESTAS SUPERFÍCIES INTERNAS DEVEM SER PERFEITAMENTE
LISAS P/ ACEITAR SOMENTE POLIMENTO



ERA20°E	D	21-11-85	VIDROS VITON LTOA	S	<i>Hydro</i>
33095	ON 4, 1/8		VIDE ANOT.	1	<i>Hydro</i>
ERA 7716,	B		DELIVERY EQUIPMENT D.G.	2	
114119129/32E 1/16	A		8 SECT. IN LINE 1.5 MACHINE	3	191-6613
ERA CHARA			TROUGH N° 0 & 2-D.G.	4	
N=11 (120)			SECT. 2 & 7 UPPER & LOWER	5	191-1548
ERA 12					
1/8 1.96					
25.7.89					
DATA					