


Drawing Number		HF-1203	
Change Description & Reason		Change Letter	
3/4 WAS 7/8		C	
1/2 WAS 5/8		C	
Reason: TO REDUCE MFG. COSTS & BROKEN TAPS		C	
Effectivity		Type	
1. Pattern		1. Pattern	
2. Material		2. Material	
3. Dimension		3. Dimension	
4. Finish		4. Finish	
5. Heat Treatment		5. Heat Treatment	
6. Coating		6. Coating	
7. Assembly		7. Assembly	
8. Disassembly		8. Disassembly	
9. Storage		9. Storage	
10. Inspection		10. Inspection	
11. Shipping		11. Shipping	
12. Receiving		12. Receiving	
13. Use		13. Use	
14. Maintenance		14. Maintenance	
15. Repair		15. Repair	
16. Disposal		16. Disposal	



PREFERRED MAT'L: ACl GRADE HH TYPE 2
 SUBSTITUTE MAT'L: AISI TYPE 309

6 HOLES
 TAP DRILL $\frac{3}{4}$ DEEP
 10-24 N.C. TAP $\frac{1}{2}$ DEEP
 CULTRAL A MACARICO AUT.
 HF-1203-M

NAME		LOWER BEARING RACE	
ALL FINISHED FRACTIONAL DIMENSIONS .007		DRAWN J. SCOTT	
UNLESS SPECIFIED FINISHED SURFACE ROUGHNESS 125		DATE 1-17-69	
CHANGES		SCALE 1-HALF	
		MATERIAL SEE NOTE	
		MARK PART NUMBER AT (X)	
		OWENS-ILLINOIS, INC.	
		DRAWING NUMBER	
		HF-1203	

USED ON ASSEMBLY NO HF-0114