


- 1. Table of Contents (This Page) Created on Mon Sep 15 13:49:55 2014
- 2. component
- 3. solder
- 4. GND
- 5. power
- 6. plated-drill
- 7. componentmask
- 8. soldermask
- 9. topsilk
- 10. bottomsilk
- 11. toppaste
- 12. topassembly
- 13. bottomassembly
- 14. fab














```
:::
:::
:::
                           ::::
```

















There are 6 different drill sizes used in this layout, 284 holes total Symbol Diam. (Inch) Count Plated?  $\frac{\text{Symbol}}{\text{YES}} = \frac{\text{B.820}}{219} \frac{\text{YES}}{\text{YES}}$ 

		x x	+ + + + + + + + + + + + + + + + + + +	* + + + + + + + + + + + + + + + + + + +	→
Title: (unknown) - Fabrication Drawing Anthor: Readles Worles	Date: Mon 15 Sep 2014 06:49:55 PM GMT UTC Maximum Dimensions: 6580.808080 mils wide, 4945.808080 mils high		*** *** *** ***	* * * * * * * * * * * * * * * * * * *	<i>&gt;</i>
YES		*	>>> >>> >>> >>> >>>	+ + +	<b>* * * * * * * * * *</b>
8 8 7		* * * * * * * * * * * * * * * * * * *			
0.035 0.848 0.845	0.075 0.081	++ +++			+++
+ × •	□ >>	<b>&gt;</b>			