




- 1. Table of Contents (This Page) Created on Sun Jan 12 13:51:53 2014
- 2. component
- 3. solder
- 4. GND
- 5. power
- 6. plated-drill
- 7. componentmask
- 8. soldermask
- 9. topsilk
- 10. bottomsilk
- 11. toppaste
- 12. topassembly
- 13. bottomassembly
- 14. fab


























this layout, 145 holes tota	
es used in	Plated?
drill siz	Count
re 5 different	Diam. (Inch)
There ar	Symbol

					high	* * * * * * * * * * * * * * * * * * *	
					888 mils	> >	+ +
					0.000	⊁ ⊁	× × +
					, 414	>	× ×
				T UTC	e wide	* * * * * * * * * * * * * * * * * * *	× ×
		Drawing		3 PM GM	30000 mils	>	× ×
		Title: (unknown) - Fabrication Drawing	-ley	Date: Sun 12 Jan 2014 07:51:53 PM GMT UTC	Maximum Dimensions: 4920.888888 mils wide, 4140.888888 mils high	>>>>	≻ +
) - Fa	ey Won	lan 20	nsion	* * *	
		knowr	Bradle	n 12 J	n Dime	>	
		Title: (un	Author: Bradley Worley	Date: Su	Maximun	*	
						>	}
ומופס:	YES	YES	YES	YES	YES	** * *	>
Coon	116	18	00	2	\vdash	*	* * * * * *
	20	35	40	31	30	++ >>> ++ >>> ++ >>> ++ >>> ++ >>> ++	*
מו	0.020	0.035	0.040	0.081	0.100	>	
oduna	>	+	×	۰	0	* *	