


- 1. Table of Contents (This Page) Created on Thu Sep 4 16:19:26 2014
- 2. component
- 3. solder
- 4. GND
- 5. power
- 6. plated-drill
- 7. componentmask
- 8. soldermask
- 9. topsilk
- 10. bottomsilk
- 11. toppaste
- 12. topassembly
- 13. bottomassembly
- 14. fab














```
:::
    :::
    :::
                               ::::
```

















There are 6 different drill sizes used in this layout, 286 holes total  $\frac{\text{Symbol}}{\text{y}}$  Diam. (Inch)  $\frac{\text{Dout}}{221}$   $\frac{\text{Plated?}}{\text{YES}}$ 

					x x x x x x x x x x x x x x x x x x x	<b>&gt;</b>	+ + +   +    ***  ***  ***  ***  ***  *	+	<b>&gt;</b> + + + + + + + + + + + + + + + + + + +
	. 6 4 - 0 4 - 1 2 7 7	nike: Unknown) - Fabricaion Drawing Author: Bradlev Worlev	Date: Thu 84 Sep 2814 89:19:26 PM GMT UTC	Maximum Dimensions: 6580.88888 mils wide, 4945.888888 mils high			*** *** *** ***	* * * * * * * * * * * * * * * * * * * *	<b>&gt;</b>
					> + + + + > > > > > > > > > > > > > > >		*** *** *** ***	+ + + + + + + + + + + + + + + + + + + +	
2 5	Y F S	YES	YES	YES	>+	<b>&gt;</b> -		+ +	> >>>> >>>>
1 0	d 6	o m	- 2	9	**	· -			
20.0	0.635	8.848 8.845	0.075	0.081	++ +++	<b>&gt;</b>			+ + + + +
	+ >	. •	0	<b>&gt;</b>	<b>&gt;</b>				