



- 1. Table of Contents (This Page) Created on Sun Oct 5 19:02:26 2014
- 2. component
- 3. solder
- 4. GND
- 5. power
- 6. plated-drill
- 7. componentmask
- 8. soldermask
- 9. topsilk
- 10. bottomsilk
- 11. toppaste
- 12. topassembly
- 13. bottomassembly
- 14. fab
































There are 6 different drill sizes used in this layout, 291 holes total  $\frac{Symbol}{v}$   $\frac{Diam. (Inch)}{0.028}$   $\frac{Count}{226}$   $\frac{Plated?}{YES}$ 

						× ×	}⊳- + + +		<b>&gt;</b> +
					*	× × ++	* ** ** ** ** ** ** ** **	*	> >
				daddd mils high	> >	<b>&gt;</b>		* ***	<b>&gt;</b>
	Title: (unknown) - Fabrication Drawing	Worley	Date: Mon 86 Oct 2814 12:82:27 AM GMT UTC	l'laximum Dimensions: 0.300.000000 mils wide, 4743.000000 mils high	, , , , , , , , , , , , , , , , , , ,	+	*** *** *** ***	+ + + +	
	Title: (unknown) -	Author: Bradley Worley	Date: Mon 86 Oct	Maximum Dimens	* *	*	* * * * * * * * * * * * * * * * * * *	+ + + + +	**
YES	YES	YES	YES	TES	> + + + + > > > + + + + >>	> <sub>&gt;</sub>		+ + +	> >>>> >>>>
46	8	e	Ν (	٥	* * **			<b>&gt;</b>	+ +
0.035	0.040	0.045	0.075	0.081	++ +++ >>> +++ >>> +++	*		<b>≻</b>	+ + +
- +	×	۰	_ )	→		»		ı	