













Aviation Investigation Notification

Location: Clarksburg, CA Accident Number: DCA24LA316

Date & Time: September 19, 2024, 12:47 Local Registration: N12125

Aircraft: Boeing 757-224 Injuries: 1 Serious, 3 Minor,

151 None

Flight Conducted Under: Part 121: Air carrier - Scheduled

The NTSB is conducting a <u>Class 4 investigation</u> into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:BoeingRegistration:N12125Model/Series:757-224Aircraft Category:Airplane

Amateur Built:

Operator: United Airlines Operating Certificate(s) Flag carrier (121)

Held:

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site: Condition of Light:

Observation Facility, Elevation: Observation Time:

Distance from Accident Site: Temperature/Dew Point:

Lowest Cloud Condition: Wind Speed/Gusts, Direction: /,

Lowest Ceiling: Visibility:

Altimeter Setting: Type of Flight Plan Filed:

Departure Point: Newark, NJ (EWR) **Destination:** San Fransisco , CA (SFO)

Wreckage and Impact Information

Crew Injuries:	2 Minor, 4 None	Aircraft Damage:	None
Passenger Injuries:	1 Serious, 1 Minor, 147 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Serious, 3 Minor, 151 None	Latitude, Longitude:	38.443739,-121.55165 (est)

Administrative Information

Investigator In Charge (IIC):	Silva, Sathya
Additional Participating Persons:	Scott Turner; United Airlines David Keenan; FAA Nathan Williams; Boeing
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.

Page 2 of 2 DCA24LA316