



# Guide PTFE tube Creality k1



VIEW IN BROWSER

updated 25. 6. 2023 | published 25. 6. 2023

## **Summary**

did a simple mod to help with the load and unload of the filament, it also makes that the filament goes more easy.

<u>3D Printers</u> > Accessories

Tags: ptfeguide k1 max holder ptfe creality ptfetube

guide

Easy to print and helps alot at the moment of the filament change, it also helps at the underextrusion, the filament goes streight and smooth.

you will need supports, infill i did 40% and no problems.

### **Model files**

holder-ptfe-k1.stl



## License **G**



This work is licensed under a Creative Commons (4.0 International License)

#### Attribution—Noncommercial—Share Alike

- **≭** | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- **×** | Commercial Use
- **≭** | Free Cultural Works
- **×** | Meets Open Definition