Amador Valley High School Classroom Building

Amador Valley High School Classroom Building												
Description	Status	Performed?	Date Sent	GC Notice 2	GC Notice 3		T&M #	Invoice	GC#	TOTALS	Amnt Approved	Difference
CO1: New framing for eletrical panels, RFI 53	sent	×	9/21/2021			1				\$6,714.32		
CO2: Installation of 3x nailer at roof perimeter	VOID	×				2				\$14,235.10	Rejected	
per 18/A8.2 along gridlines 1 & 4		**				-					,	
CO3: Per RFI 51 - Replace 3-1/2" square x 1/2"		• •	9/21/2021									
washer in lieu of 2-1/2" square x 1" washers at	sent	×	9/21/2021			3				\$895.40		
HSS columns CO4: Frame dropped ceilings at rooms 1-109, 1-												
	VOID	×				4				\$6,559.30	Rejected	
108, 1-106, 1-107 CO5: 6" SDS screws where we can not place the												
L50 clip at all door and window openings	sent	×	9/21/2021			5				\$4,981.90		
CO6: Per engineers field report, at elevator												
machine room	sent	×	9/21/2021			6				\$1,542.48		
CO7: Per engineers field report, provide L50												
framing clips each side of LVL blocking	sent	×	9/21/2021			7				\$7,139.88		
CO8: Per RFI#51, Tie Down Detail - Windows. At TD												
hardware (HDU11 & HDU14) use 1/4" diameter x 5"		×	9/21/2021			8				\$8,367.70		
long Simpson SDS screws in lieu of the specified 2	sent	^	9/21/2021			۰				\$8,307.70		
1/2" long screws.												
	sent	×	9/21/2021			9				\$4,414.63		
Per RFI 65 - projector backing per sketch provided												
RFI 84 - Sunshade Support	sent	×	9/21/2021			10				\$7,263.63		
New framing for relocating eletrical panels, Per	sent		11/12/2021				1			\$6,714.32		
RFI# 53.		. //	44 /42 /2024				2			* COOF 40		
Per RFI#57	sent	<b>4</b>	11/12/2021 11/12/21				3			\$895.40		
Per RFI# 93 Per engineers field report at elevator machine	sent		11/12/21				5			\$4,981.90		
room	sent	✓	11/12/21				6			\$1,553.48		
Per engineer's field report, provide L50 framing												
clips	sent		11/12/21				7			\$7,139.88		
Per RFI#51	sent	<b>V</b>	11/12/21				8			\$8,367.70		
Per RFI 65	sent	Ý	11/12/21				9			\$4,414.89		
Per RFI 84	sent	<b>V</b>	11/12/21				10			\$7,263.63		
Reframe mechanical closets 13" bigger.	sent	<b>V</b>	9/21/2021				11			\$9,134.40		
Installation of ML28 clips at SW33 shear walls												
second floor not noted on plans. Per engineer	sent	✓	9/21/2021				12			\$1,665.40		
walk.												
Additional nailing to shear wall connections	sent	<b>√</b>	9/21/2021				13			\$2,209.35		
beyond scope of work, Per engineers request.	Sent	*	3/21/2021				13			92,20J.JJ		
RFI#85	done	<b>V</b>							2	\$5,000.00	\$5,000,00	\$0.00
The second secon										1-7	30.00	
CHANGE ORDER TOTALS								\$	59,340.3	\$5,000.00		