


USB-C: 5 V in (data pins unused)




CH32V003: I2C to the sensor, WS2812 cheeks




SCD40: CO2, temperature, humidity




Left cheek: WS2812C-2020




Right cheek: WS2812C-2020



The 'O' mouth: boop for temperature, then humidity



Power flags



Generated from blocks -> design.json by heypcb-kicad

HeyPCB method / pure KiCad

Sheet: /

File: air_ghost.kicad_sch

Title: Air Ghost – desk CO2 / temperature / humidity monitor, SCD40, USB-

Size: A3	Date: 2026-10-05	**Rev: A**
KiCad E.D.A. 10.0.6		Id: 1/1