

ADDITIONAL RISK EXAMPLES

Sales Risk Examples:

Products/Services Overpriced
Products/Services Underpriced
Customer Requirements Unclear
Slow Quote
Didn't quote

Purchasing Risk Examples:

Overpay
Order Incorrectly
Late Delivery
Wrong Product Delivered
Substandard or Defective Materials

Production Risk Examples:

Wrong material used
Incorrect dimensions
Incorrect tolerances
Manufactured to obsolete drawing
Contamination

Inspection Risk Examples:

Reject good product
Accept bad product
Miss inspection point
Unable to perform inspection

Delivery Risk Examples:

Lost in shipment
Damaged in shipment
Delivered to incorrect location
Late Delivery
Stolen