

8.4.2. Type of Extent Control

The organization is required to ensure that externally provided processes, products and services do not adversely affect its ability to consistently deliver conforming products and services to its customers.



- ✓ Check of products at delivery
- ✓ Site acceptance tests
- ✓ Second-party supplier audits

If supplier audits are required, this should be written in to the contracts with the suppliers.

Risk-Based Thinking

Externally provided processes, products and services must remain under the organization's QMS control through documented information

- ✓ Supplier
 - ✓ Date
 - ✓ Purchase Order Number
 - ✓ Items required
 - ✓ Quantities
 - ✓ Required delivery date
 - ✓ Quoted prices where applicable or known
 - ✓ Any other information deemed critical for the supply of the material should also be noted.
- 

Auditing

- ✓ Review documented information (a list) indicating which are the approved external providers and that this documented information is kept up to date
- ✓ Orders have been placed to external providers satisfying the defined criteria
- ✓ There is effective performance of outsourced processes
- ✓ The activities necessary for ensuring that the specified requirements have been met are carried out
- ✓ Verify that risk based thinking has been applied by an organization in determining appropriate controls over external providers