



Incident ID: 6a2f9f31b0f0f7cefe65e000 | Report Status: RESOLVED | Generated: 6/15/2026 | Verification ID: e0c642cea507d081faa8a67b383a810b

SECTION 1 EXECUTIVE SUMMARY

Incident ID	6a2f9f31b0f0f7cefe65e000
Type	Natural Disaster - Earthquake
Severity	3

SECTION 2 INCIDENT DETAILS

Created At	6/15/2026, 6:44:01 AM
Resolved At	6/15/2026, 6:47:21 AM
Status	RESOLVED

SECTION 3 TRAIN & CREW

Train Number	785655
Affected Component	Front Section of Train

SECTION 4 SUPERVISION

Reported By	Krishna Choudhary
Lead Supervisor	N/A

SECTION 5 RESOURCE DEPLOYMENT

#	Operator Name	Emp ID	Designation	Duty	Accept.	Arrived	Done
1	Aniruddha Sharma	N/A	Operator	Response	6:44:21 AM	-	-

SECTION 6 CASUALTY

Fatalities	0
Injuries	0

SECTION 7 TIMELINE

#	Event	Timestamp	Elapsed	Remarks
1	Incident Created	6:44:01 AM	0 min	Reported by supervisor
2	Incident Resolved	6:47:21 AM	3 min	Marked resolved

SECTION 7B OPERATOR RESPONSE LOGS

7B.1 — Acceptance Log



Incident ID: 6a2f9f31b0f0f7cefe65e000 | Report Status: RESOLVED | Generated: 6/15/2026 | Verification ID: e0c642cea507d081faa8a67b383a810b

Operator	Accepted At	ART Arrived	Duration (min)	Status
Aniruddha Sharma	6:44:21 AM	-	-	PENDING

7B.3 — Response Time Log (Site)

Operator	Accepted At	Site Arrived	Duration (min)	Status
Aniruddha Sharma	6:44:21 AM	-	-	PENDING


SECTION 8 LOCATION


Latitude	22.738137
Longitude	75.863075

SECTION 9 EVIDENCE SUMMARY

Evidence Type	Count	Integrity Status
Photographs	3	VERIFIED
Videos	1	VERIFIED
Audio	1	VERIFIED
Text Statements	0	VERIFIED

SECTION 10 TEXT STATEMENTS**SECTION 11 PHOTOGRAPHIC EVIDENCE**

	Timestamp: 6/15/2026, 6:44:47 AM GPS: 22.7283176, 75.8748217 Device: motorola moto g(9) Captured By: Aniruddha Sharma Photo #1
---	--

	Timestamp: 6/15/2026, 6:45:31 AM GPS: 22.7283123, 75.8748081 Device: motorola moto g(9) Captured By: Aniruddha Sharma
---	---



Incident ID: 6a2f9f31b0f0f7cefe65e000 | Report Status: RESOLVED | Generated: 6/15/2026 | Verification ID: e0c642cea507d081faa8a67b383a810b




Photo #3

SECTION 12 VIDEO EVIDENCE**[PLAY]**

Duration: N/A
Timestamp: 6/15/2026, 6:45:03 AM
GPS: 22.7283268, 75.8748709
Captured By: Aniruddha Sharma

[VIDEO] VIDEO #1**SCAN TO VIEW**

Or visit:
<https://res.cloudinary.com/dixdw1mus/video/upload/v1781505911/RapidResponse/incidents/6a2f9f31b0f0f7cefe65e000/proofs/6a2d9b30243a9ae31e0d2635/bv5zd6j58vk4sryvd41a.mp4>

SECTION 13 AUDIO EVIDENCE**[AUDIO] AUDIO RECORDING #1**

Timestamp: 6/15/2026, 6:45:43 AM
Captured By: Aniruddha Sharma

**SCAN TO
LISTEN****Direct URL:**

<https://res.cloudinary.com/dixdw1mus/video/upload/v1781505950/RapidResponse/incidents/6a2f9f31b0f0f7cefe65e000/proofs/6a2d9b30243a9ae31e0d2635/f2yr9kkwxerbo4vmx2c.mp4>

SECTION 14 ROOT CAUSE**Description**

Pending detailed analysis

SECTION 15 CORRECTIVE ACTIONS**Actions Taken**

Site secured, team deployed

SECTION 16 APPROVALS & SIGN-OFF**Prepared By****Supervisor Approval****Lead Supervisor Approval**

Name: Krishna Choudhary

Name: Krishna Choudhary

Name: Pending



Incident ID: 6a2f9f31b0f0f7cefe65e000 | **Report Status:** RESOLVED | **Generated:** 6/15/2026 | **Verification ID:** e0c642cea507d081faa8a67b383a810b

