

# July 2025 Tech Meeting

Welcome to our monthly technical review and planning session

## Meeting Agenda

NPS score

June's Winner, Winner Branch, Need to increase NPS score

HASS

NEED TO INCREASE HASS PERCANTAGE


Information

T-con data update, MPU Saw

Training

STG Monthly Training, SPSN Training Video, Service bulletin








#### Winner Branch: MD

The rule is changed for Best Performed Office on NPS.

HSN will grant \$500 for Branch Manager + Top 3 technicians who scored over 70 of the branch. And it started from March's NPS result.


## Need to increase NPS score



Target Goal: Score 75

Our NPS score has increased by 70.9 points compared to last month, Reaching a new high of 0.46. This achievement reflects your hard work and dedication. Thank you for making this possible.


# Need to IMPROVE HASS percentage



#### Target Goal: 80 Percentage

Our June HASS percentage is **77.23**. Based on the 3-month average analysis, the result is 77.21%, significantly below Samsung's target of 80%. **It's critical that we improve our HASS percentage to meet expectations.** Dedicated and continuous efforts to enhance performance are not only encouraged but essential.

#### T-con Data Update





<USB Drive>

We've ordered USBs for each branch for the purpose of T-con data update. Please kindly make sure to review 'How to download the SW for T-Con data update.ppt' file. It show you how to download SW on your work phone at the site

#### HA MPU SAW POLICY

## HA and Monitor should also receive MPU SAW

- ☐ We need to get an MPU SAW specifically for HA and Monitor for the repair operations.
- ☐ Please be extremely careful, as this is a mandatory requirement.
- ☐ Also, ensure you have reviewed the 'Multiple Parts Usage Policy HA'.

Refrigerator			
Part 1 & Part 2	Instruction		
*ASSY COVER DISP* & *ASSY PCB KIT LED*	Should not be changed in the same repair		
*ASSY COVER DISP* & *ASSY PCB KIT	Should not be changed in the same repair		
*ASSY COVER DISP* & *WINDOW-COVER DISPENSER*	Should not be changed in the same repair		
*ASSY PCB KIT LED* & *WINDOW-COVER DISPENSER*	Should not be changed in the same repair		
*ASSY DOOR FOAM FRE*	More than 1 of this part should not be used in the same repair		

Oven		
Part 1 & Part 2	Instruction	
*ASSY COOKTOP* & *ASSY-FRAME COOKTOP*	Should not be changed in the same repair	
*ASSY DRAWER* & *ASSY-SLIDER LEFT*	Should not be changed in the same repair	
*ASSY DRAWER* & *ASSY-SLIDER RIGHT*	Should not be changed in the same repair	
*ASSY COOKTOP FRAME*	More than 1 of this part should not be used in the same repair	
*ASSY COOKTOP*	More than 1 of this part should not be used in the same repair	
*ASSY DRAWER*	More than 1 of this part should not be used in the same repair	

Dishwasher			
Part 1 & Part 2	Instruction		
*ASSY BASE" & *ASSY SUMP-MODULE"	Should not be changed in the same repair		
*ASSY BASE* & *ASSY BASE*	Should not be changed in the same repair		
*ASSY COVER PCB* & *ASSY PCB EEPROM*	Should not be changed in the same repair		
*ASSY DISPLAY* & *ASSY-PANEL CONTROL*	Should not be changed in the same repair		
*ASSY MOTOR BLDC* & *ASSY SUMP-MODULE"	Should not be changed in the same repair		
*ASSY SUMP-MODULE" & *MOTOR BLDC PUMP*	Should not be changed in the same repair		
*ASSY-BASKET LOWER A* & *BASKET-LOWER A*	Should not be changed in the same repair		
*ASSY-BASKET LOWER A* & *COVER-PWZ-AREA*	Should not be changed in the same repair		
*ASSY-BASKET LOWER A* & *HANDLE-BASKET A-U*	Should not be changed in the same repair		
*ASSY-BASKET LOWER A* & *HOLDER-TINE L*	Should not be changed in the same repair		
*ACCV DANIEL CONTROL * 9. *CURDE LED LUDDENI*	Charild and he shound in the same reasis		



### STG Monthly Training



Understanding KPI BE Required Training July 2025

Complete your STG Monthly Training. Must finish by 7/23.



Smart Things BE required Training Jul 2025

Complete your STG Monthly Training. Must finish by 7/23.



STG Smart Service FE Required Training Jul 2025

Complete your STG Monthly Training. Must finish by 7/23.

#### **ASSIGNED / NO DUE DATE**

Understanding KPI BE Required Training Jul 2025

In Progress

000

Open Curriculum

Smart Things BE required Training Jul 2025

In Progress

000

**Open Curriculum** 

STG Smart Service BE Required Training Jul 2025

Registered

000

Launch

SAMSUNG TECHNICAL ASSESSMENT - TV

In Progress

000


Open Curriculum

#### SPSN Training Video

You can find training videos on the Samsung SPSN website.

Please review them to enhance your technical skills.

• URL: <u>Samsung Product Support Network Training</u>



## Refrigerator Service Bulletin

#### Service Tip

#### SAMSUNG

Title	Beverage Center Door - Will Not Open			
Create Date	6/10/2025	Model(s) involved	RF90F, RF70F, RF29DB, RF23DB,	
Revision Date			RM80F	

Important: Service tips are published for informational purposes only and are intended for use only by personnel qualified for the specific tasks depicted. The information contained in this service tips does not expand or otherwise alter Samsung's standard limited warranty applicable to the product. This information is published for experienced repair technicians only and is not intended for use by the public. It does not contain warnings to advise non-technical individuals of possible dangers in attempting to service a product. Only experienced professional technicians should repair products powered by electricity. Any attempt to service or repair the product or products dealt with in this service tips by anyone else could result in serious injury or death. Information provided in this document is subject to change or update without notice.

#### Background:

Units Beverage center door will not open when latch is depressed

Root Cause – Hook Latch is bent out of spec and cannot fully disengage

#### Service Method:

Step 1: Open the Door

Use a Hook tool or flat plastic paddle to disengage the hook latch from inner door



CRITICAL ALERT: "Will Not Open" Issue

When servicing this model, it is absolutely mandatory to review the Service Bulletin before you go.



# Thank you