

Tech Meeting

May 2026


Home Service Network

April Winners



Congratulations to our outstanding performers !
Cheonho Lee and **Marcos Villar** were each granted \$1000.

April Winner Branch: PAP



HSN will grant \$500 to the Branch Manager and
Top 3 technicians (**Denny Jang, Andrey Yakushev and Andy Son**) Congratulations!

April SBB Winners



Congratulations to our outstanding performers !

Douglas Balcom, Pilyoun Jung, Hyeonho Ki and Rohan Brown were each granted \$1000!

STG Process for Installation Issue

Reminder:

STG Process for Identifying Installation Related Issues -Update to required Process
As of 6/1 /23 - This has been a required process to avoid warranty payment rejections.

As announced in May 2023, capturing Installation Failures in STG is crucial to understanding where we can improve our installation process and satisfy our customers' needs better and is **now required**.

We have made this process to report an Installation Issue/Failure **even easier** for your techs. Please take a moment to share this information with your technicians as soon as possible.


IMPROVEMENTS:

1. The Installation Issue/Failure flag; has been moved to the main ticket screen in your techs ticket view in STG
2. Purchase date/production date of the model is no longer a factor. Any repair in which a cosmetic or function issue was caused by improper installation or delivery should be flagged using this process.

Make sure to proceed STG Process for Installation Issue!!

Simple steps:

1. "Installation Fault" button
2. "Installation Related Repair"
3. Proceed to follow the prompts
4. Add pictures
➤ Submit



Note: There is no approval needed or further action requested. This step is to simply notify Samsung of the installation issue

*If the ticket is not eligible based on production date a pop up will appear after selecting Installation Related Repair.

****PCR Service Mandatory Notice****

- **For IH PCR : 43, 50, 55, 58, 60, 65**

All PCR services will be handled In-Home !

Samsung has issued a directive requiring that PCR service transition from pick-up to in-home service. While we have made efforts to delay this change, it can no longer be postponed. Accordingly, all technicians will be required (without exception) to perform PCR service in-home in the near future.

In the interim, while PCR service continues via pick-up, all technicians are expected to utilize the TVs brought into the office to practice and develop their PCR skills. This will help ensure a smooth and timely transition to in-home service.

Please be advised that in-home PCR service is not optional; it is a mandatory work requirement for all technicians.

PCR Service Notice



Primer handling guide :

<http://69.74.172.226:5000/sharing/05sNj8zlL>

Panel Component Repair :

<http://69.74.172.226:5000/sharing/wiIe6RN6s>

Open cell repair guide :

https://players.brightcove.net/1366266421001/dz7WPjL3O_default/index.html?videoId=6390735936112



Primer handling guide




Panel Component Repair




Open cell repair guide

OTWEU OOW Exception for SC4U (CLPW) covers parts and labor, except for SSR



< Mobile version >



< Web site >

OTWEU OOW Exception for SC4U (CLPW) will cover Parts and Labor, except for SSR which over 5 years from DOM

***** SC4U (CLPW) refers to a Customer Pre-Paid Samsung Out-of-Warranty (OOW) fee *****
Please DO NOT offer any additional OOW charges to the customer if the ticket is under SC4U (CLPW).
If you have any questions, please feel free to contact the Triage Team.
SC4U (CLPW) : We do not process the SSR service over 5 years from the Date Of Manufacture (DOM)

HSN New Policy Update for unmount and mount unit

• Service Guidelines: Mounting & Safety

1. Preparation & Accessibility

- Service Area: The unit must be accessible and free of obstructions.
- Unmounting: If the unit is mounted and cannot be unmounted by the Tech or the Customer, document the issue, complete the ticket, and advise the customer to contact Samsung for a new request.
- Liability Waiver: A signed waiver is mandatory before any unmount/remount work.
 - If refused: Note the refusal, complete the ticket, and refer the customer to Samsung.

2. Safety Restrictions (Do Not Proceed)

Complete the ticket and advise the customer to contact Samsung if:

- Height Limit: The anchor point or center of the TV is higher than 5 feet from the floor.
- Obstructions: Any physical barriers prevent a safe unmount/remount.
- Lack of Assistance: The customer provides no help for unmounting when required.

3. Second-Man Documentation

If a second person is required, you must include:

- A clear statement that a second man was used.
- Full Name and Phone Number of the second person.

Prepaid Payment Policy for Out-of-Warranty Services

Please be advised that the following policy regarding out-of-warranty service tickets is mandatory and not optional:


1. Full payment is required and must be received before any service or part replacement is performed.
2. If payment is refused or not received, service will not be provided under any circumstances.
3. For any repair involving part replacement, the full cost of the part must be paid in advance prior to proceeding with the repair.
4. This policy must be followed at all times and cannot be overridden by a technician's discretion or a customer's request.
5. No exceptions will be permitted unless formal prior approval is obtained from management.
6. For prepaid service tickets, the company has already collected the initial service fee from the customer; therefore, technicians may not refuse to visit the customer's home.

***** This policy is mandatory, effective immediately, and applies to all out-of-warranty service tickets. *****

NPS Notice

(NPS: Net Promoter Score)

Company KPI Trend



Our NPS score continues to fall short of the target. Last month, we recorded an NPS of 64.0, which was below our goal.

As the importance of NPS is constantly highlighted, we ask that everyone gives this their full attention.


April NPS: 64.0

NPS Target goal: 70

HASS Notice



Company KPI Trend



Starting September, your HASS usage percentage will directly affect your compensation. Please note that if your HASS usage is below 75%, you will not be eligible for compensation.

April HASS: 79.9%

HASS Target goal: 80%

The HASS usage trend is improving. Last month, the usage rate reached 79.9%. Please continue this progress and ensure we meet the 80% target.

If the following issues occur while using HASS:

- 1. App closes during report transmission
- 2. Pending report does not transmit after failure

Users must send error information via Configuration > Management > Send error information to the HASS admin.

The system will automatically attach the log to the administrator’s account for email submission.

***Important:** The error log must be sent within 10 minutes of the issue. After 10 minutes, the log will be automatically deleted.

How to Count and Manage NPS Score

(NPS: Net Promoter Score)

*NPS score count: Total Survey Rate score/Survey count = NPS score

Survey Rate score 10 to 9 = +100 pts

Survey Rate Score 8 to 7 = 0 pts

Survey Rate Score 6 to 1 = -100 pts

Please explain to the customer that the Samsung Survey is all about the **Technician** and has nothing to do with **the product** or the **Customer Service Representative (CSR)**.


If the customer is satisfied with the service but dislikes the other situation or other complaints, Please let the customer know that on Survey, there are writing comment section on the survey after giving out the Survey Rating Score between 9 and 10.



Smart Service

Count of Latest Ticket	Column Labels		
Row Labels	O	X	Grand Total
HOME SERVICE NETWORK, NC	3	5	8

→ Using rate is currently **38%**



Product Support recommendation!

Starting now, we are implementing a Smart Service system, When viewing the ticket list, **If you see a red stamp, it is very important that you click the ‘Contents’ button and check the details.**

Once the content has been reviewed, the red stamp will automatically change to green, indicating that confirmation is complete.

Please note that blue stamps do not require any action.

However, RED STAMP MUST BE CHECKED, and you must make sure they have changed to green after reviewing the content.

if you see a red stamp, Click the ‘Contents’ button and check the details

Kashif Paul
Aug 1, 8:00 AM
(240) 855-1514
7700 DOWN CT, LAUREL MD

DW80CG4051SR LP
AA Warranty

TICKET UPDATE 4181799
768

Customer Sign

SMS Chat **Contents** ...

Kashif Paul
Aug 1, 8:00 AM
LAUREL, MD

4181799768

Action Req ☐

Contents ☒

Parts ☒

Photo Upload

TCC Support Request

Once the contents are reviewed, the stamp will turn green

Kashif Paul
Aug 1, 8:00 AM
(240) 855-1514
7700 DOWN CT, LAUREL MD

DW80CG4051SR LP
AA Warranty

TICKET UPDATE 4181799
768

Customer Sign

SMS Chat **Contents** ...

You don't need to do anything for the blue stamp

Kashif Paul
Aug 1, 8:00 AM
(240) 855-1514
7700 DOWN CT, LAUREL MD

HASS

1. Ticket Completion (Mobile .ver)

Please Check the information below before completing the ticket!

HSN Service Report 105

4184

Pending

BFSC105

Grigory Guz

08:00 ~ 09:00 AM @ Marlboro Township

DVG47CG3500VA3 (SAMSUNG)

Details Parts Tracking Chat Billing

*** REDO *** Previous Ticket: 4184
*** Installation Problem Target ***

Quick Action

Not Completed Completed

General Information

Status Pending Sync

Sub Status Requested info. from customer (Spec, Tech)

Status Comment Edit

Customer Information

Customer Grigory Guz Liability Waiver

Home Phone 609-230-7433

Cell Phone 1 609-230-7433

Cell Phone 2

Work Phone

Address 347 Van Dusen Dr Marlboro Township NJ 07746

On my way Check In Check Out

Cx Email 1 gregguz55@gmail.com

Cx Email 2

Serial No JKQB4BBR100599X [Verified by Serial]

Purchase Date

Extra Information Update

Property	Value	Actions
		>Add

Symptom & Repair Guide

Service Type In Home

Symptom 23 - Noise / Vibration 04 - When dispensing ice 01 - Grinding noise

Remark

Defect * APPR (Appearance Item Defect) Fan noise

Repair * DPRT (DEFECTIVE PART REPLACEMENT) Part replaced

Report Installation Problem Repair

Inquiry & Resolution New

Comment

[2026-04-20 null] CX Portal Trip Fee Payment Submitted: 130.35 USD
[2026-04-20 Mhel Chulani] CX PREPAID TRIP FEE UPFRONT: \$130.35

Repair History

Ticket #	Branch	Completed	Defect	Repair
No repair history found				

Copy New Save

Symptom & Repair Guide

New Inquiry

Save

Problem Repair


Inquiry & Resolution New

Check "Inquiry & Resolution"
(Ticket > Detail > Inquiry & Resolution > Click "New")
*Make sure to input the proper documentation on the inquiry!


Scroll down

1. Ticket Completion (Mobile .ver)

Please Check the information below before completing the ticket!



Check "Parts" (Ticket > Parts> Click "Parts")
*Check part status, delete not used parts, and leave the used parts!
*Proper notes including Part #, Invoice #, Unique ID needed!



Check "Tracking"
(Ticket > Tracking > Attachments > Click "New Samsung Picture")
*Make sure proper pictures are uploaded!

1. Ticket Completion (Mobile .ver)

HSN

Service Report

105

MD
2 days
REDO
IW

4184

Pending

BFSC105

Grigory Guz

08:00 ~ 09:00 AM @ Marlboro Township

DVG47CG3500VA3 (SAMSUNG)

Details

Parts

Tracking

Chat

Billing

*** REDO *** Previous Ticket: 4184
*** Installation Problem Target ***

Quick Action

Not Completed

Completed

General Information

StatusPendingSync

Sub StatusRequested info. from customer (Spec, Tech)

Status CommentEdit

Customer Information

CustomerGrigory GuzLiability Waiver

Home Phone609-230-7433

Cell Phone 1609-230-7433

Cell Phone 2

Work Phone

Address347 Van Dusen Dr Marlboro Township NJ 07746

On my way

Check In

Check Out

Cx Email 1gregguz55@gmail.com

Cx Email 2

Serial NoJKQB4BBR100599X[Verified by Serial]

Purchase Date

Check S/N

Extra Information

Update

Property	Value	Actions
		>Add

Symptom & Repair Guide

Service TypeIn Home

Symptom23 - Noise / Vibration04 - When dispensing ice01 - Grinding noise

Remark

Defect

Repair

* APPR (Appearance Item Defect)

Fan noise

* DPRT (DEFECTIVE PART REPLACEMENT)

Part replaced

Report Installation Problem Repair

Inquiry & Resolution

New

Comment

New

[2026-04-20 null] CX Portal Trip Fee Payment Submitted: 130.35 USD

[2026-04-20 Mhel Chulanil] CX PREPAID TRIP FEE UPFRONT: \$130.35

Repair History

Ticket #

Branch

Completed

Defect

Repair

No repair history found

Copy New

Save

CLICK!

1. Input "Defect code"

(★ : most common reason used by technicians)

2. Input "Defect description"

3. Input "Repair code"

(★ : most common reason used by technicians)

4. Input "Repair description"

5. Click "Save" to save the information.

Scroll down

1. Ticket Completion (Mobile .ver)

HSN

Service Report

105

4184

MD
2 days
REDO
IW

Pending

BFSC105

Grigory Guz

08:00 ~ 09:00 AM @ Marlboro Township

DVG47CG3500VA3 (SAMSUNG)

Details

Parts

Tracking

Chat

Billing

*** REDO *** Previous Ticket: 4184
*** Installation Problem Target ***

Quick Action

Not Completed

Completed

General Information

Status

Pending

Syn

Sub Status

Requested info. from customer (Spec, Tech)

Status Comment

Edit

Customer Information

Customer

Grigory Guz

Liability Waiver

Home Phone

609-230-7433

Cell Phone 1

609-230-7433

Cell Phone 2

Work Phone

Address

347 Van Dusen Dr Marlboro Township NJ 07746

On my way

Check In

Check Out

Cx Email 1

gregguz55@gmail.com

Cx Email 2

Repair Report

New Picture

1. Choose Repair Certainty

1

50%

2

75%

3

100%

2. Enter the symptom and resolution

Symptom*

Resolution*

☐ empty

Internal Note

3. Parts Used

0 record found

Status	Part No	Invoice #
	Description	Qty

Submit

1. Click “Completed”
2. Fill out and submit the “Repair Report”.
3. *Please ensure all the info previously mentioned in the ticket details is included—keep in mind that the Repair Report is different from the ticket details.

2. Ticket Pending (Mobile .ver)

HSN

Service Report

105

MD
2 days
REDO
IW

4184

Pending

BFSC105

Grigory Guz

08:00 ~ 09:00 AM @ Marlboro Township

DVG47CG3500VA3 (SAMSUNG)

Details

Parts

Tracking

Chat

Billing

*** REDO *** Previous Ticket: 4184
*** Installation Problem Target ***

Quick Action

Not Completed

Completed

General Information

Status

Pending

Sync

Sub Status

Requested info. from customer (Spec, Tech)

Status Comment

Edit

Customer Information

Customer

Grigory Guz

Liability Waiver

Home Phone

609-230-7433

Cell Phone 1

609-230-7433

Cell Phone 2

Work Phone

Address

347 Van Dusen Dr Marlboro Township NJ 07746

On my way

Check In

Check Out

Cx Email 1

gregguz55@gmail.com

Cx Email 2

General Information

Status

Pending

Sub Status

Requested info. from customer (Spec, Tech)

Status Comment

Re-visit required (Wrong information)

Repair complete pending warranty error

Repair In Progress After Parts Receive

Customer Information

Customer

Requested info. from customer (Spec, Tech)

Home Phone

SAW Requested

Cell Phone 1

Shipback

Cell Phone 2

Tech Support needed

Work Phone

Ticket has been updated, ASC to review

Address

Ticket status Discrepancy

Cx Email 1

UPS Damage

Cx Email 2

Waiting for OOW payment

Product Information

Waiting for Product Arrival

REDO Ticket

Waiting for Samsung FOC/Discount Approval

Waiting for warranty documents (POP/BOS)

1. Input Status as “Pending”
2. If the tech must revisit the Cx, set the reason as:
 “Requested info. from Customer”
3. If the ticket cannot be completed or an error code occurs:
 → Please reach out to Triage !

[SAMSUNG] Final Ticket Management Guide ■

As Samsung concludes the four-part Ticket Management series, we want to stress the importance of having as much information as possible included in the ticket detail, before the ticket is closed.

- **Picture Model/Serial Number Tag**
- **Signed Customer Work order**
- **Picture of Unit**
- **Pictures of any pre-existing damage to unit or area around unit**
- **HASS OQC Success Report**

Repair Part Information		You have 1 parts [DG47-00067A]		Disty Part Tracking	Related Repair History	Parts & Repair Tips	Part List	Create Po
Attachment		You have 8 files		Insert(Multi) Insert(Single)				
	File Type	File Name	Size (MB)	Date				
1	Others	Image File	OTH_repair_completion_signature.jpg	0.02	01.07.2026 174013			
2	Others	Image File	OTH_20260108021002615.jpg	1.24	01.07.2026 211003			
3	Others	Image File	OTH_20260108021002818.jpg	1.05	01.07.2026 211004			
4	Others	Image File	OTH_20260108021003115.jpg	1.38	01.07.2026 211004			
5	Others	Image File	OTH_20260108021003303.jpg	1.2	01.07.2026 211004			
6	Others	Image File	OTH_20260108021003740.jpg	1.31	01.07.2026 211004			
7	Others	Image File	OTH_20260108021005118.jpg	1.08	01.07.2026 211005			
8	Others	Image File	OTH_20260108021005883.jpg	1.22	01.07.2026 211006			

****All tickets must be completed on-site** ■

With proper pictures and notes uploaded **

All Technicians – Please be mindful of the following:

1. All tickets must be updated and completed on-site.
2. Photos taken on-site must be uploaded immediately along with the update note.
- 3. Mandatory 4 pictures must be uploaded on the tickets**
***(Before service picture, After service picture, S/N label, HSN liability form)**
4. Make it a habit to complete tickets onsite — do not wait until the end of the day.

*If extra parts are needed for the service, Photos or needed parts must be sent through the chatroom

*** Tickets are required to be completed no later than 10 PM***

**** If tickets are not completed on time, we will be unable to process claims properly, which may result in payment delays.****



Monthly STG Training

*** Updated training must be completed by the 20th of every month. Failure to complete the training will result in a warning letter !!!

Name	Status	Product
TV Open Cell Repair BE Required Training 2026	Completed	
2026 Yearly Certification - TV	Completed	
2026 Yearly Certification - W&D	Completed	
2026 Yearly Certification - Cooking	Completed	
2026 Yearly Certification - Refrigerator	Completed	

****ATTENTION****



If any of your technicians currently do not have access to STG’s Ticket Management feature, please use the link below to let us know:

<https://www.surveymonkey.com/r/TECHVIEWSTG>

Accessing the Content on Cornerstone

In order to find the assigned courses, follow these simple steps:

1. Log into STG > ELEARNING
2. This should take you to the LMS Home Page
3. Learning → Go to View Your Transcript
4. Assigned Training (Video+ Quiz) will be shown if you have the appropriate RA’s. After the video you will then be directed to the quiz portion.



MPU SAW

Starting 7/25/2025, All HOME ELECTRONICS (HE) , HOME APPLIANCES (HA) products are subject to MPU SAW/WER.

This includes MONITOR and B2B Units as well.

If more than one part is required, please make sure to contact Technical Support (T/S) and proceed with the diagnosis together.

There is no separate T/S line for B2B units

Please continue using the existing T/S contact.

▼

Refresh

BFSC577

IW

LED TV

15d

Claimed

KKL 07/18

Tracking

Repair Parts 2

SAW 2

Compensation

Other Information

Billing

Category	Status	Requestd
SRC41	Approved	07/15/2025
Warranty Exception Request	Approved	07/17/2025

Importance of managing KPI



Samsung operates with a strong emphasis on KPI performance. In many instances, their approach may seem demanding or rigid; however, as a service provider under Samsung, we are obligated to comply with their operational guidelines and expectations.

Key performance indicators such as NPS (Net Promoter Score) and HASS are critical metrics that directly impact the volume of ticket assignments we receive. Unless we consistently meet these KPI targets, Samsung will not allocate additional tickets to us.

It is therefore imperative that all technicians make a concerted effort to improve and maintain strong KPI performance.