



Pressure Sensor 
$$P = \frac{F}{Asensor} = \frac{10}{9 \times 10^{-4}} = 1111 P_{q}$$

Flex sensor:

Electrical

