

multi hole 14x11	(a) 79	74	82	63
multi hole 16x12	54	50	56	43
multi hole 18x14	59	55	61	47
multi hole 20x15	109	102	114	88
notch 14x11	71	66	74	57
notch 16x12	165	155	172	133
notch 18x14	75	70	78	61
notch 20x15	185	173	193	149
curved hole 14x11	118	111	123	95
curved hole 16x12	161	151	168	130
curved hole 18x14	96	89	1e+02	77
curved hole 20x15	52	48	54	42
stress concentration 8x6	26	24	23	23
	mono	unload	cyclic	nonprop

(b) 10	93	5233	98
32	39	2208	32
63	65	5750	71
84	97	5993	144
82	98	4774	127
201	256	14690	371
57	66	3866	84
291	356	16008	487
143	168	7540	188
246	298	18696	399
77	88	2383	107
30	27	2308	29
24	21	611	34
mono	unload	cyclic	nonprop

(c) 6	2.2	1.9	1.6
1.8	1.8	1.6	1.2
2.9	2.1	1.8	1.9
3.3	2.6	2.5	2.4
2.9	2.4	2.3	1.9
4	2.7	3.4	2.9
3.1	2.5	2.4	2.1
3.3	2.6	2.8	2.4
2.2	1.9	1.8	1.6
2.3	1.9	1.8	1.7
2.9	2.4	2	2.1
2.7	1.9	1.7	1.7
1.3	1.1	1.1	1.1
mono	unload	cyclic	nonprop