## HONG SENG ASSEMBLY SDN BHD

## NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE	Static vertical forces : 2684 daN			
HV	Main	Emergency 1	Emergency 2	Parking Brake
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 1637 daN 60 % (2) 9 % (2) 8 %			

AXLE (1)	Left	Α	Axle		Right	
Side Slip vertical static force SERVICE BRAKE	884 0	<b>-2.</b> IaN 1787	4 m/km daN	903	daN	
wheel locked Braking force Efficiency Dissymetry	548 c 62 %	laN 1126	ight daN % %	578 64	daN %	

AXLE (2)	Left		Axle		Right	
vertical static force SERVICE BRAKE	425	daN	897	daN	466	daN
wheel locked			10	eft		
Braking force	234	daN	511	daN	277	daN
Efficiency	55	%	57	%	60	%
Dissymetry			8	%		
Unbalance			9	%		

OPACITY			
	Absorption OPACITY K	<b>12.00</b> % 0.18 m-1	
	Max engine speed	0 rpm	

000	GOOD	000 ACCEPT.	<b>000</b> BAD	(0) Axle	
		v 3.0.	6.4		PAGE 1/1