HONG SENG ASSEMBLY SDN BHD

NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

Static vertical forces : 6597 daN			
Main	Emergency 1	Emergency 2	Parking Brake
1+2 4083 daN 63 %			
	Main 1+2 4083 daN	Main Emergency 1 1+2 4083 daN 63 %	Main Emergency 1 Emergency 2 1+2 4083 daN 63 %

AXLE (1)	Le	ft	Ax:	le	Rig	ght
Side Slip vertical static force SERVICE BRAKE	2290	daN	+2.9 4622	m/km daN	2332	daN
wheel locked Braking force Efficiency Dissymetry Unbalance	1282 56	daN %	rig 2819 61 15	ht daN % %	1537 66	daN %

AXLE (2)	Le	ft	Ax	le	Rig	ght
vertical static force SERVICE BRAKE	906	daN	1975	daN	1069	daN
wheel locked			rig	ght		
Braking force	516	daN	1264	daN	748	daN
Efficiency	57	%	64	%	70	%
Dissymetry			19	%		
Unbalance			15	%		

OPACITY			
	Absorption OPACITY K	8.00 % 0.14 m-1	
	Max engine speed	0 rpm	

000 GOOD	000 ACCEPT. <u>000</u> BAD (0) Axle
	v 3.0.6.4	PAGE 1/1