## HONG SENG ASSEMBLY SDN BHD

## NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE	Static vertical forces : 2798 daN					
HV	Main	Emergency 1	Emergency 2	Parking Brake		
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 1884 daN 67 % (1) 9 % (2) 13 %					

AXLE (1)	Left		Axle		Right	
Side Slip vertical static force SERVICE BRAKE	890	daN	<b>+2.9</b> 1867	m/km daN	977	daN
wheel locked Braking force	624	daN	le 1269	ft daN	645	daN
Efficiency Dissymetry Unbalance	70	%	68 6 9	% % %	66	%

AXLE (2)	Left		Axle		Right	
vertical static force SERVICE BRAKE	452	daN	931	daN	479	daN
wheel locked			10	eft		
Braking force	327	daN	615	daN	288	daN
Efficiency	69	%	66	%	60	%
Dissymetry			13	%		
Unbalance			6	%		

OPACITY			
	Absorption OPACITY K	<b>13.00</b> % 0.19 m-1	
	Max engine speed	0 rpm	

000 GOOD	000 ACCEPT.	<b>000</b> BAD	(0) Axle	
	v 3.0.	6.4		PAGE 1/1