HONG SENG ASSEMBLY SDN BHD

NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	
	energy : Disel

VEHICLE	Static vertical forces : 2805 daN					
HV	Main	Emergency 1	Emergency 2	Parking Brake		
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 1837 daN 59 % (1) 18 % (1) 9 %					

AXLE (1)	Left		Axle		Right	
Side Slip vertical static force SERVICE BRAKE	869	daN	-2.8 1837	3 m/km daN	968	daN
wheel locked			16	eft		
Braking force	530	daN	1200	daN	649	daN
Efficiency	61	%	65	%	67	%
Dissymetry			9	%		
Unbalance			18	%		

AXLE (2)	Left		Axle		Right	
vertical static force SERVICE BRAKE	465	daN	968	daN	503	daN
wheel locked			10	eft		
Braking force	275	daN	561	daN	312	daN
Efficiency	59	%	58	%	62	%
Dissymetry			5	%		
Unbalance			8	%		

OPACITY			
	Absorption OPACITY K	15.00 % 0.21 m-1	
	Max engine speed	0 rpm	

00	0 GOOD	000 ACCEPT.	000 BAD	(0) Axle	
		v 3.0.	6.4		PAGE 1/1