HONG SENG ASSEMBLY SDN BHD

NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE	Static vertical forces : 6681 daN				
HV	Main	Emergency 1	Emergency 2	Parking Brake	
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 3968 daN 59 % (2) 6 % (2) 16 %				

AXLE (1)	Le	Left		Axle		Right	
Side Slip vertical static force	2300	daN		m/km daN	2370	daN	
SERVICE BRAKE wheel locked Braking force Efficiency Dissymetry Unbalance	1498 65	daN %	le 2802 60 15	ft daN % %	1304 55	daN %	

AXLE (2)	Left		Axle		Right	
vertical static force SERVICE BRAKE	976	daN	2011	daN	1035	daN
wheel locked Braking force Efficiency Dissymetry Unbalance	514 53	daN %	ri 1166 58 16	ght daN % %	652 63	daN %

OPACITY			
	Absorption OPACITY K	15.00 % 0.19 m-1	
	Max engine speed	0 rpm	

000 GOO	DD 000 ACCEPT.	000 BAD	(0) Axle	
	v 3.0	.6.4		PAGE 1/1