HONG SENG ASSEMBLY SDN BHD

NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

ZUL
energy : Disel

VEHICLE	Static vertical forces : 2290				
HV	Main	Emergency 1	Emergency 2	Parking Brake	
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 1415 daN 61 % (2) 17 % (2) 11 %				

AXLE (1)	Le	ft	Ax	le	Rig	ght
Side Slip vertical static force	774	daN	-2.3 1589	m/km daN	815	daN
SERVICE BRAKE wheel locked			le	ft		
Braking force	538	daN	1100	daN	562	daN
Efficiency	70	%	69	%	69	%
Dissymetry			1	%		
Unbalance			4	%		

AXLE (2)	Le	ft	Ах	le	Rig	ght
vertical static force SERVICE BRAKE	342	daN	701	daN	359	daN
wheel locked Braking force	166 49	daN	365	eft daN	199	daN
Efficiency Dissymetry Unbalance	49	%	52 11 17	% % %	55	%

OPACITY			
	Absorption OPACITY K	11.00 % 0.24 m-1	
	Max engine speed	0 rpm	

000 GOOD	000 ACCEPT.	000 BAD	(0) Axle	
v 3.0.6.4				