HONG SENG ASSEMBLY SDN BHD

NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE	Static vertical forces : 6615 daN					
HV	Main	Emergency 1	Emergency 2	Parking Brake		
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 3781 daN 58 % (2) 13 % (1) 16 %					

AXLE (1)	Left		Axle		Right	
Side Slip vertical static force SERVICE BRAKE	2325	daN	+3.2 4700	m/km daN	2375	daN
wheel locked Braking force Efficiency Dissymetry Unbalance	1183 51	daN %	rig 2632 56 16 4		1449 61	daN %

AXLE (2)	Left		Axle		Right	
vertical static force SERVICE BRAKE	895	daN	1915	daN	1020	daN
wheel locked			16	eft		
Braking force	546	daN	1149	daN	603	daN
Efficiency	61	%	60	%	59	%
Dissymetry			3	%		
Unbalance			13	%		

OPACITY			
	Absorption OPACITY K	10.00 % 0.18 m-1	
	Max engine speed	0 rpm	

00	0 GOOD	000 ACCEPT.	000 BAD	(0) Axle	
	V 3.0.6.4				PAGE 1/1