HONG SENG ASSEMBLY SDN BHD

NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE				
HV	Main	Emergency 1	Emergency 2	Parking Brake
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 3874 daN 59 % (2) 11 % (1) 7 %			

AXLE (1)	Left		Axle		Right	
Side Slip vertical static force SERVICE BRAKE	2251	daN		m/km daN	2377	daN
wheel locked Braking force Efficiency Dissymetry Unbalance	1350 60	daN %	le 2684 58 7 5	ft daN % %	1334 56	daN %

AXLE (2)	Left		Axle		Right	
vertical static force SERVICE BRAKE	932	daN	1983	daN	1051	daN
wheel locked				left		
Braking force	568	daN	1190	daN	622	daN
Efficiency	61	%	60	%	59	%
Dissymetry			3	%		
Unbalance			11	%		

OPACITY			
	Absorption OPACITY K	11.00 % 0.18 m-1	
	Max engine speed	0 rpm	

000 G	GOOD 6	000 ACCEPT.	000	BAD	(0) Axle	
v 3.0.6.4						PAGE 1/1