HONG SENG ASSEMBLY SDN BHD

NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE	Static vertical forces : 2811 daN						
HV	Main	Emergency 1	Emergency 2	Parking Brake			
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 1837 daN 59 % (1) 23 % (1) 4 %						

AXLE (1)	Left		Axle		Right	
Side Slip vertical static force SERVICE BRAKE	890	daN	-2.6 1865	5 m/km daN	975	daN
wheel locked			16	eft		
Braking force Efficiency	587 65	daN %	1274 57	daN %	687 70	daN %
Dissymetry Unbalance			7 23	%		

AXLE (2)	Left		Axle		Right	
vertical static force SERVICE BRAKE	495	daN	946	daN	451	daN
wheel locked			10	eft		
Braking force	285	daN	563	daN	278	daN
Efficiency	58	%	60	%	61	%
Dissymetry			4	%		
Unbalance			17	%		

OPACITY			
	Absorption OPACITY K	9.00 % 0.13 m-1	
	Max engine speed	0 rpm	

06	0 GOOD	000 ACCEPT.	000 BAD	(0) Axle	
		v 3.0.	6.4		PAGE 1/1