## HONG SENG ASSEMBLY SDN BHD

## NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE	Static vertical forces : 2811 daN					
HV	Main	Emergency 1	Emergency 2	Parking Brake		
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 1837 daN 59 % (1) 23 % (1) 4 %					

AXLE (1)	Le	ft	Ax	le	Rig	ght
Side Slip vertical static force SERVICE BRAKE	890	daN	<b>-2.6</b> 1865	m/km daN	975	daN
wheel locked Braking force	587	daN	1274	eft daN	687	daN
Efficiency Dissymetry Unbalance	65	%	57 7 23	% % %	70	%

AXLE (2)	Le	ft	Ах	cle	Rig	ght
vertical static force SERVICE BRAKE	495	daN	946	daN	451	daN
wheel locked Braking force	285	daN	16 563	eft daN	278	daN
Efficiency Dissymetry	58	%	60	% %	61	%
Dissymetry Unbalance			17	%		

OPACITY			
	Absorption OPACITY K	9.00 % 0.13 m-1	
	Max engine speed	0 rpm	

000 GOOD	000 ACCEPT. <u>000</u> BAD (	0) Axle
	v 3.0.6.4	PAGE 1/1