## HONG SENG ASSEMBLY SDN BHD

## NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE	Static vertical forces : 6597 daN			
HV	Main	Emergency 1	Emergency 2	Parking Brake
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 4083 daN 63 % (2) 15 % (2) 19 %			

AXLE (1)	Left	Axle	Right
Side Slip vertical static force	2290 da	<b>+2.9</b> m/km N 4622 daN	2332 daN
SERVICE BRAKE wheel locked Braking force Efficiency Dissymetry Unbalance	1282 da 56 %	right N 2819 daN 61 % 15 % 2 %	1537 daN 66 %

AXLE (2)	Le	ft	A>	cle	Rig	ght
vertical static force SERVICE BRAKE	906	daN	1975	daN	1069	daN
wheel locked			rig			1
Braking force Efficiency	516 57	daN %	1264 64	daN %	748 70	daN %
Dissymetry			19	%		
Unbalance			15	%		

OPACITY			
	Absorption OPACITY K	8.00 % 0.14 m-1	
	Max engine speed	0 rpm	

000 GOOD	<b>000</b> ACCEPT. <b>000</b> BAD	(0) Axle
	v 3.0.6.4	PAGE 1/1