## HONG SENG ASSEMBLY SDN BHD

## NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	
	energy : Disel

VEHICLE	2875 daN			
HV	Main	Emergency 1	Emergency 2	Parking Brake
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 1749 daN 59 % (2) 9 % (2) 7 %			

AXLE (1)	Left Ax			le	Right	
Side Slip vertical static force SERVICE BRAKE	919	daN	<b>-2.7</b> 1887	/ m/km daN	968	daN
wheel locked Braking force	582	daN		ft daN	593	daN
Efficiency Dissymetry Unbalance	63	%	62 3 2	% %	61	%

AXLE (2)	Left		Axle		Right	
vertical static force SERVICE BRAKE	488	daN	988	daN	500	daN
wheel locked			1.	eft		
Braking force	274	daN	574	daN	300	daN
Efficiency	56	%	58	%	60	%
Dissymetry			7	%		
Unbalance			9	%		

OPACITY			
	Absorption OPACITY K	<b>12.00</b> % 0.29 m-1	
	Max engine speed	0 rpm	

00	<b>0</b> GOOD	000 ACCEPT.	<b>000</b> BAD	(0) Axle	
		v 3.0.	6.4		PAGE 1/1