HONG SENG ASSEMBLY SDN BHD

NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE	Static vertical forces : 6697 daN			
HV	Main	Emergency 1	Emergency 2	Parking Brake
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 4145 daN 63 % (2) 7 % (2) 12 %			

AXLE (1)	Lef	t	Ax:	le	Rig	ght
Side Slip vertical static force	2320	daN		m/km daN	2368	daN
SERVICE BRAKE wheel locked Braking force Efficiency Dissymetry Unbalance	1392 60	daN %	rig 2860 61 3	ht daN % %	1468 62	daN %

AXLE (2)	Le	ft	Ах	le	Rig	ght
vertical static force SERVICE BRAKE	968	daN	2009	daN	1041	daN
wheel locked			le	ft		
Braking force	660	daN	1285	daN	625	daN
Efficiency	68	%	64	%	60	%
Dissymetry			12	%		
Unbalance			7	%		

OPACITY			
	Absorption OPACITY K	11.00 % 0.23 m-1	
	Max engine speed	0 rpm	

000 GOOD	000 ACCEPT. 000 BAD	(0) Axle
	v 3.0.6.4	PAGE 1/1