## HONG SENG ASSEMBLY SDN BHD

## NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE	Static vertical forces : 2340					
HV	Main	Emergency 1	Emergency 2	Parking Brake		
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 1415 daN 63 % (2) 17 % (2) 27 %					

AXLE (1)	Left		Axle		Right	
Side Slip vertical static force SERVICE BRAKE	805	daN	<b>-2.1</b> 1646	m/km daN	841	daN
wheel locked			le	ft		
Braking force Efficiency	533 66	daN %	1074 65	daN %	541 64	daN %
Dissymetry Unbalance			3 1	% %		

AXLE (2)	Left		Axle		Right	
vertical static force SERVICE BRAKE	314	daN	694	daN	380	daN
wheel locked Braking force	194	daN	16 341	eft daN	147	daN
Efficiency Dissymetry	62	%	49 27	% %	39	%
Unbalance			17	%		

OPACITY		,	
	Absorption OPACITY K	<b>15.00</b> % 0.27 m-1	
	Max engine speed	0 rpm	

000 GOOD	<b>000</b> ACCEPT. <b>000</b> BAD	(0) Axle	
	v 3.0.6.4		PAGE 1/1