HONG SENG ASSEMBLY SDN BHD

NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE	Static vertical forces : 2805 daN					
HV	Main	Emergency 1	Emergency 2	Parking Brake		
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 1837 daN 59 % (1) 18 % (1) 9 %					

AXLE (1)	Left		Axle		Right	
Side Slip vertical static force SERVICE BRAKE	869	daN	-2.8 1837	m/km daN	968	daN
wheel locked Braking force Efficiency	530 61	daN %	le 1200 65	eft daN %	649 67	daN %
Dissymetry Unbalance	01	76	9	% %	07	76

AXLE (2)	Left		Axle		Right	
vertical static force SERVICE BRAKE	465	daN	968	daN	503	daN
wheel locked Braking force	275	daN	16 561	eft daN	312	daN
Efficiency Dissymetry	59	%	58 5	% %	62	%
Unbalance			8	%		

OPACITY			
	Absorption OPACITY K	15.00 % 0.21 m-1	
	Max engine speed	0 rpm	

000 GOOD	000 ACCEPT. 000 BAD	(0) Axle	
	v 3.0.6.4		PAGE 1/1